

		<p>抽查照片</p> <p>拍攝日期： 109 年 11 月 2 日</p>
<p>拍攝內容： 0K+250 左側路燈</p>		

說明：基座接地測試，設計：電阻 $<50\Omega$ ；實際：電阻 15Ω ，符合。

		<p>抽查照片</p> <p>拍攝日期： 109 年 11 月 2 日</p>
<p>拍攝內容： 0K+288 左側路燈</p>		

說明：基座接地測試，設計：電阻 $<50\Omega$ ；實際：電阻 13Ω ，符合。

